



Load Testing, Inspection & Rigging
608 Hangar Drive • New Iberia, LA 70560
Phone (337) 365-1022 • Fax (337) 365-1024
Toll Free (877) 246-3905

N N^o 54013

NDT FIELD INSPECTION REPORT

Customer: National Welding Supply Job. #: 062811-
 Ordered By: Jessie Date: 28 Jun 11
 RIG/OCS-G: _____ Specification: BS EN 12079
 P.O. #: _____ DNV 2.7-1
 OTHER _____

Magnetic Particle (MT)

Procedure Used _____ REV _____
 Wet _____ Dry _____ Cont _____
 AC _____ DC _____ Residual _____
 Yoke# _____ Demagnetized Yes No
 Coil# _____
 UV Lamp Intensity _____ UW/CM2 W/L Intensity _____ fc
 Bath Strength _____ % 100 ML Tube
 White Contrast Batch # _____
 Particle Batch # _____

Dye Penetrant (PT)

Procedure Used _____ REV _____
 W/L Intensity _____ FC
 Developer BATCH# _____
 Dye BATCH# _____

Visual Inspection (VT)

Procedure Used VT-P-001 REV 02
 W/L Intensity 100 FC

ITEM DESCRIPTION Bottle rack SERIAL # 1965

(VT only)
 VT padare welds and load bearing welds
 and entire visible structure

Accepted

Tyler Beaul

ASNT / TC — IA LEVEL II INSPECTOR