



Load Testing, Inspection & Rigging
608 Hangar Drive • New Iberia, LA 70560
Phone (337) 365-1022 • Fax (337) 365-1024
Toll Free (877) 246-3905

N No 53619

NDT FIELD INSPECTION REPORT

Customer: NWS Job. #: _____
 Ordered By: Jonathan Date: 19 July 11
 RIG/OCS-G: _____ Specification: BS EN 12079
 P.O. #: _____ DNV 2.7-1
 OTHER _____

Magnetic Particle (MT)

Procedure Used _____ REV _____
 Wet _____ Dry _____ Cont _____
 AC _____ DC _____ Residual _____
 Yoke# _____ Demagnetized Yes No
 Coil# _____
 UV Lamp Intensity _____ UW/CM2 W/L Intensity _____ fc
 Bath Strength _____ % 100 ML Tube
 White Contrast Batch # _____
 Particle Batch # _____

Dye Penetrant (PT)

Procedure Used _____ REV _____
 W/L Intensity _____ FC _____
 Developer BATCH# _____
 Dye BATCH# _____

Visual Inspection (VT)

Procedure Used VT-P-001 REV 02
 W/L Intensity _____ FC _____

ITEM DESCRIPTION Bottle Rack SERIAL # NWS 1387

VT only

VT on entire visible structure

OK

Perry Baptiste

ASNT / TC — IA LEVEL II INSPECTOR